

# Quick Test Results

1/20 ↑

P0320      ENG \$00


Ignition /

Distributor Engine

Speed Input Circuit ↓

MIL

**AutoScanner® Plus**




# Quick Test Results

P2106            ENG \$00    ↑  
Throttle Actuator  
Control System -  
Forced Limited  
Power                            ↓  
MIL

**AutoScanner® Plus**







## Quick Test Results

4/20 ↑

P0174      ENG \$00


Bank 2 System Too

Lean

PENDING



**AutoScanner® Plus**



# Quick Test Results

5/20↑

P0175      ENG \$00

Bank 2 System Too

Rich


PENDING



**AutoScanner® Plus**







# Quick Test Results

P0606      ENG \$00    ↑  
Engine Control  
Module / Powertrain  
Control Module  
Processor      ↓  
PENDING

**AutoScanner® Plus**



## Quick Test Results

P1000                      ENG \$00                      †  
On Board  
Diagnostics II  
Monitor / Drive  
Cycle Test Not                      †  
Complete

**AutoScanner® Plus**






## Quick Test Results

P2105            ENG \$00    ↑  
Throttle Actuator  
Control System -  
Forced Engine  
Shutdown                    ↓

**AutoScanner® Plus**





# Quick Test Results

P2106            ENG \$00    ↑  
Throttle Actuator  
Control System -  
Forced Limited  
Power                            ↓  
PENDING

**AutoScanner® Plus**







## Quick Test Results

P0320            MOD \$00    ↑  
Ignition /  
Distributor Engine  
Speed Input Circuit  
CONFIRMED                    ↓

**AutoScanner® Plus**




## Quick Test Results

P0606            MOD \$00    ↑  
Engine Control  
Module / Powertrain  
Control Module  
Processor            ↓  
CONFIRMED

**AutoScanner® Plus**





# Quick Test Results

P2106 MCD \$00 †  
Throttle Actuator  
Control System -  
Forced Limited  
Power ‡  
CONFIRMED

**AutoScanner® Plus**




# Quick Test Results

P0174            MOD \$00    ↑  
Bank 2 System Too  
Lean  
PENDING

16/20    ↓

**AutoScanner® Plus**






# Quick Test Results

P0175                      MOD \$00    ↑  
Bank 2 System Too  
Rich  
PENDING

17/20 ↓

**AutoScanner® Plus**



## Quick Test Results

P0320                      MOD \$00

Ignition /


Distributor Engine

Speed Input Circuit

PENDING

**AutoScanner® Plus**





## Quick Test Results

P0606 MOD \$00

Engine Control

Module / Powertrain


Control Module

Processor

PENDING



**AutoScanner® Plus**




## Quick Test Results

P2106                      MOD \$00  
Throttle Actuator  
Control System -  
Forced Limited  
Power  
PENDING

AutoScanner® Plus






## Quick Test Results

P2198                      MOD \$00  
Oxygen Sensor  
Signal Biased /  
Stuck Rich Bank 2  
Sensor 1  
PENDING

**AutoScanner<sup>®</sup> Plus**



## Quick Test Results

P2198 MOD \$00

Oxygen Sensor

Signal Biased /


Stuck Rich Bank 2

Sensor 1

PENDING

**AutoScanner® Plus**





## Quick Test Results

### Code Summary



ABS	No codes
OBDII/EOBD	9 code(s)
ENG	11 code(s)

**AutoScanner® Plus**